

	Type	Hits	Search Text	DBs	Time Stamp
1	IS&R	321	(219/73.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/26 09:09
2	IS&R	38	(219/73.11).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/26 09:05
3	IS&R	194	(219/137.61).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/26 09:06
4	IS&R	1241 69	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/26 09:09
5	BRS	1	S4 and ((consum\$5 near5 (guide or tube) near10 (slag or electroslag) near10 weld\$3) near20 (flux or insulator)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/26 09:16
6	BRS	9	S4 and ((consum\$5 near5 (guide or tube) near10 (slag or electroslag or flux or insulator) near10 weld\$3)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/26 09:18
7	BRS	9	((consum\$5 near5 (guide or tube) near10 (slag or electroslag or flux or insulator) near10 weld\$3)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/26 09:18

	Type	Hits	Search Text	DBs	Time Stamp
8	BRS	10	((consum\$5 near20 (guide or tube) near50 (slag or electroslag or flux or insulator) near50 weld\$3)).clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2006/07/26 09:19